

User's Manual

Handheld Digital Precision Manometer

GMH3160-07

-10,0 to 350,0 mbar relative

Version 4.7



CONTENTS

1	GENERAL.....	2
1.1	SAFETY REQUIREMENTS	2
1.2	OPERATION AND MAINTAINANCE ADVICE	3
1.3	CONNECTIONS	3
1.4	DISPLAY.....	3
1.5	BASIC OPERATION.....	3
2	CONFIGURATION	4
2.1	UNIT: COICE OF THE DISPLAY UNIT	4
2.2	P.OFF: AUTO POWER OFF TIME	4
2.3	ADR: BASE ADDRESS OF INTERFACE	4
3	ERROR AND SYSTEM MESSAGES	4
4	PRESSURE CONNECTION TO THE SENSORS	5
5	CALIBRATION SERVICES	5
6	THE SERIAL INTERFACE	5
7	SPECIFICATION.....	6

1 General

1.1 Safety Requirements

This device has been designed and tested in accordance with the safety regulations for electronic devices. However, its trouble-free operation and reliability cannot be guaranteed unless the standard safety measures and special safety advises given in this manual will be adhered to when using the device.

1. Trouble-free operation and reliability of the device can only be guaranteed if the device is not subjected to any other climatic conditions than those stated under "Specification".
2. Device and sensors have to be handled with care (don't throw, hit, etc.). Protect plugs and sockets from soiling.
3. If the device is transported from a cold to a warm environment condensation may cause in a failure of the function. In such a case make sure the device temperature has adjusted to the ambient temperature before trying a new start-up.
4. If device is to be connected to other devices (e.g. via serial interface) the circuitry has to be designed most carefully. Internal connection in third party devices (e.g. connection GND and earth) may result in not-permissible voltages impairing or destroying the device or another device connected.

Warning: If device is operated with a defective mains power supply (e.g. short circuit from mains voltage to output voltage) this may result in hazardous voltages at the device (e.g. at sensor socket or interface).

5. If there is a risk whatsoever involved in running it, the device has to be switched off immediately and to be marked accordingly to avoid re-starting.

Operator safety may be a risk if:

- there is visible damage to the device
- the device is not working as specified
- the device has been stored under unsuitable conditions for a longer period of time.

In case of doubt, please return device to manufacturer for repair or maintenance.

1.2 Operation And Maintenance Advice

• Battery Operation

If Δ and 'bAt' are shown in the secondary display the battery has been used up and needs to be replaced. The device will, however, operate correctly for a certain amount of time. If 'bAt' is shown in the upper display the voltage is too low to operate the device; the battery has been completely used up.


Please note: We recommend to take out battery if device is not used for a longer period of time!

• Mains Operation With Power Supply

Warning: When using a power supply please note that operating voltage has to be 10.5 to 12 V DC. Do not apply overvoltage!! Cheap 12V-power supplies often have excessive no-load voltage. We, therefore, recommend using regulated voltage power supplies. Trouble-free operation is guaranteed by our power supply GNG10/3000.

Prior to connecting the power supply to the mains make sure that the operating voltage stated at the power supply is identical to the mains voltage.

1.3 Connections




Connection for pressure tubes: „+“ = higher pressure, „-“ = lower pressure
Interface: Connection for el. isolated interface adapter (p.r.t. chapter 6)
The mains adapter socket is located at the left side of the device.

1.4 Display

Units: an arrow points to the chosen measuring unit

Tara: appears if tara-function is activated.

SL: no function



main display: shows measuring value.

Δ : indicates weak battery or other warnings


secondary display: min-, max- or hold value

Logg: no function

AL: no function

1.5 Basic Operation

When switching on the device and a zero point adjustment was carried out it shows shortly „nuLL Corr“.



On-/Off-Switch

Tara: Calling of tara function, zero point adjustment

min/max: Showing the min- resp. max-memory in sec. display

Store/Quit: Calling of hold function

Set/Menu: Calling of configuration

Max Memory: Pressing 'max' (key 2) shows the maximum of the measured values. Pressing it again hides it. To clear the max memory press key 'max' for >2 seconds.

Min Memory: Pressing 'min' (key 5) shows the minimum of the measured values. Pressing it again hides it. To clear the min memory press key 'min' for >2 seconds.

Hold Function: By pressing 'Store/Quit' (key 6) the last measuring value will be held in the secondary display. Pressing it again hides it.

Tare Function: By pressing 'Tara' (key 3) the display will be set to 0. All measurings from then on will be displayed relatively to the set tare value. When tara function is activated, the arrow "Tara" appears in the display. To deactivate tare function press 'Tara' for >2 seconds.

Please Note: Activating/deactivating tara clears the max- & min-memories.

Zero-Point Adjustment: If there is no pressure applied to the pressure ports the device will display 0. If there is a permanent deviation (and device is operated under steady conditions), a permanent zero point adjustment can be carried out. To carry out the adjustment press key 3 for 5 seconds.

(Please note: A zero-point adjustment can only be carried out if the difference between the value on display and the value calibrated on site is less than 2%! E.g. for the measuring range of -10.0 ..+350.0mbar, =>zero-point adjustment up to 7.0mbar possible)

To recall the manufacturer's calibration press button 3 for approx. 7 seconds.

Note: If a zero-point adjustment was carried out, this will be signalled by the short displaying of „NuLL Corr“ when switching on the device.

2 Configuration

To change device settings, press **Menu** (key 4) for 2 seconds. This will call the configuration menu. Pressing key **Menu** jumps between the parameters.

The parameters can be changed with **▲** (key 2) or **▼** (key 5).

Quit (key 6) finishes the configuration and returns to standard measuring operation.

2.1 Unit: Coice Of The Display Unit



Choose the desired display unit, the refering unit is displayed by means of a functional arrow in the display. The selection is permanently stored in the device, therefore after power on the unit will instantly reappear. The choice depends on the used sensor.

The unit [m] =mH₂O is just supported by devices with [m] printed below the display!

2.2 P.oFF: Auto Power Off Time



The device will be automatically switched off if no key is pressed/no interface communication takes place for the time of the power off time.

The power off time can be set to values between 1 and 120 min. It can be completely deactivated by setting the paramter to „P.oFF = oFF“.

2.3 Adr: Base Address of Interface



Up to 10 devices of the GMH3xxx- handheld-family can be connected to a serial interface at once (depending on interface converter, e.g. GRS3105: 5 devices). To get access to each device the base addresses of the devices have to be different. For example choose 01 for the first, 11 for the second device and so on.

3 Error And System Messages

Display	Meaning	What to do?
	Low battery power, device will only continue operation for a short period of time	Replace battery
	Battery empty	Replace battery
	Mains operation without battery: wrong voltage	Check power supply, replace it when necessary
No display or confused characters, device does not react on keypress	Battery empty Mains operation without battery: wrong voltage or polarity System error Device defective	Replace battery Check power supply, replace it when necessary Disconnect battery and power supplies, wait shortly, then reconnect Return to manufacturer for repair
Err.1	Measured value above allowable range Sensor defective	Check: pressure above 350mbar? -> measuring value to high Return to manufacturer for repair
Err.2	Measured value below allowable range Sensor defective	Check: pressure below -10mbar? -> measuring value to high Return to manufacturer for repair
Err.4	Value is too low to be displayed, tara is set	Check: display below -2000 (tara?)?
Err.9	Measured value far out of allowable range	Check: pressure not within sensor range?
Err.7	System error	Return to manufacturer for repair

4 Pressure Connection To The Sensors

- **For measurements of over pressure (-10.0mbar...350.0mbar):**
Connect plastic tube with internal dia of 4 mm to pressure port "+". Port "-" will not be used!
- **For measurements of under pressure (-350.0mbar...0.0mbar):**
Plug the tube to pressure port "-". The measuring range covers then -350.0 to 0.0 mbar.
Note: All values are displayed now as positive values. No minus sign will be shown.
Example: it is possible to measure under pressure down to -350.0 mbar, the display shows then the value 350.0 (no minus sign).
- **For measurements of pressure differences:**
Connect both plastic tubes with an internal dia of 4 mm to pressure port "+" and "-"; make sure to apply higher pressure to port "+".

5 Calibration Services

Calibration certificates – DKD-certificates – other certificates:

If device should be certified for its accuracy, it is the best solution to return it with the referring sensors to the manufacturer.

Only the manufacturer is capable to do efficient recalibration if necessary to get results of highest accuracy!

6 The Serial Interface

By means of the serial interface and a suitable electrically isolated interface adapter (GRS3100 or GRS3105) the device can be connected to a computer for data transfer. With the GRS3105 up to 5 devices of the GMH3xxx- series can be connected to one interface (see also manual of GRS3100 or GRS3105). To avoid transmission errors, there are several security checks implemented e.g. CRC.

The following standard software packages are available:

- **EBS9M:** 9-channel software to display the measuring values
- **EASYCONTROL:** Universal multi channel software (EASYBUS-, RS485-, or GMH3000- operation possible) for real-time recording and presentation of measuring data of one GMH3xxx device in the ACCESS®-data base format

In case you want to develop your own software we offer a **GMH3000-development package** including:

- a universally applicable Windows functions library ('GMH3000.DLL') with documentation that can be used by the most programming languages.
- Programming examples Visual Basic 4.0, Testpoint (Keithley Windows measuring software)

Note: *The measuring and display range values read back from the interface are always in the selected measurement unit (mbar, bar...)!*

Supported functions:

Code	Name/Function	Code	Name/Function
0	Read measurement value	194	Set display unit
3	Read system state	199	Read kind of measuring of display
6	Read min memory	200	Read min display range
7	Read max memory	201	Read max display range
12	Read ID number	202	Read display range - unit
174	Clear min memory	204	Read display range – decimal point
175	Clear max memory	208	Read # of channels
176	Read min measuring range	222	Read power off time (Conf-P.oFF)
177	Read max measuring range	223	Set power off time (Conf-P.oFF)
178	Read measuring range – measuring unit	240	Reset
179	Read measuring range – decimal point	254	Program version
180	Read kind of measuring of sensor		

7 Specification

Measuring ranges:

Display range:	-10.0 to 350.0 mbar relative (under pressure down to -350.0 mbar, p.r.t. chapter 5)
Overload:	max. 1000 mbar rel. (without destruction or recalibration of sensor being necessary)
Resolution:	0.1 mbar (10 Pa)
Pressure units:	mbar, bar, kPa, MPa, mmHg, PSI mH ₂ O (only for devices with ,m' printed below display), selectable
Accuracy: (typ.)	±0,2%FS (hysteresis and linearity) ±0,4%FS (temperature dependency 0-50°C) OPTION higher accuracy: ±0.1%FS (hyst., lin.) ±0.4%FS (temp. dep. 0-50°C)
Measuring rate:	4 meas./sec
Nominal temperature:	25°C

Sensor: Piezo-resistive relative pressure sensor integrated in device. Suitable for air and non-corrosive and non-ionizing gases and liquids.
(Not suitable for water – use air buffering)

Connection: 2 metal pressure ports for connection to 6 x 1 mm tubes at the top of device (4mm inner tube Ø)

Power-Off-Function: Device will be automatically switched off if no key is pressed/no interface communication takes place for the time of the power-off delay. The power-off delay can be set to values between 1 and 120 min.; it can be completely deactivated.

Display: 2 four digit LCDs (12.4mm high and 7 mm high) for measuring values, and for min/max memories, hold function, etc. as well as additional functional arrows.

Pushbuttons: 6 membrane keys

Interface: Serial interface (3.5mm jack) can be connected to RS232 interface of a PC via electrically isolated interface adapter GRS3100 or GRS3105 (see accessories).

Power supply: 9V battery, type: IEC 6F22 (included in scope of supply)
as well as additional d.c.connector (diameter of internal pin 1.9 mm) for external 10.5-12V direct voltage supply. (suitable power supply: GNG10/3000)

Power consumption: Slow measuring rate: < 1.2 mA

Low battery warning: -display and ' bAt '

Housing: impact-resistant ABS, membrane keyboard, transparent panel, Front side IP65
Dimensions: 142 x 71 x 26 mm (L x W x D) + metal pressure ports 11mm at top of device
Working temperature: 0...+50°C
Allowable rel. humidity: 0...95 % r.H. (not condensing)
Storage temperature: -20...+70°C

EMC: The GMH3160-07 device corresponds to the essential protection ratings established in the Regulations of the Council for the Approximation of Legislation for the member countries regarding electromagnetic compatibility (89/336/EWG).

Additional fault: <1%